



Montage du boîtier	Schéma de perçage	Alésage de fixation ø x T mm
à visser TH 42	 <p>Diagram showing a circular hole with diameter ø 35. The distance from the center of the hole to the center of the top hole is 5,5. The distance from the center of the hole to the center of the bottom hole is 52. The distance from the left edge of the hole to the center of the top hole is C. The diameter of the top hole is ø x T. The diameter of the bottom hole is ø x T.</p>	
à enfoncer TH 43		ø 10 x 11
Montage rapide Fix TH 45		ø 10 x 6
avec manchons à expansion prém. TH 48		ø 10 x 11
	 <p>Diagram showing a circular hole with diameter ø 35. The distance from the center of the hole to the center of the top hole is 9,5. The distance from the center of the hole to the center of the bottom hole is 45. The distance from the left edge of the hole to the center of the top hole is C. The diameter of the top hole is ø x T. The diameter of the bottom hole is ø x T.</p>	
à enfoncer TB 43		ø 8 x 11
Montage rapide Fix TB 45		ø 8 x 6
avec manchons à expansion prém. TB 48	ø 8 x 11	